



FIG. 1




2/11

FIG. 2




3/11

FIG. 3



4/11

FIG. 4




5/11

FIG. 5

h	COE(1)	COE(2)	COE(3)	COE(4)	COE(5)	COE(6)	COE(7)	COE(8)
	COE(9)	COE(10)	COE(11)	COE(12)	COE(13)	COE(14)	COE(15)	
h1(-1)	0.0017	-0.0038	0.0083	-0.0162	0.0299	-0.0562	0.1350	0.9739
	-0.1028	0.0475	-0.0257	0.0138	-0.0069	0.0031	-0.0015	
h1(-2)	0.0049	-0.0112	0.0239	-0.0458	0.0839	-0.1624	0.4632	0.7798
	-0.1980	0.0979	-0.0533	0.0283	-0.0137	0.0060	-0.0032	
h2(-1)	-0.0015	0.0031	-0.0069	0.0138	-0.0257	0.0475	-0.1028	0.9739
	0.1350	-0.0562	0.0299	-0.0162	0.0083	-0.0038	0.0017	
h2(-2)	-0.0032	0.0060	-0.0137	0.0283	-0.0533	0.0979	-0.1980	0.7798
	0.4632	-0.1624	0.0839	-0.0458	0.0239	-0.0112	0.0049	

6/11

FIG. 6




$(a-1) \rightarrow (a-2)$	$(-6.88) - (-6.63) = -0.25$
$(b-1) \rightarrow (b-2)$	$(-7.12) - (-7.37) = 0.25$

(C) CHANGE OF PHASE CHARACTERISTIC (FLAT BAND)


7/11

FIG. 7



8/11

FIG. 8



9/11

FIG. 9





FIG. 11



10/11

FIG. 10

